Sanitized Copy Approved for Release 2011/09/19: CIA-RDP78-03424A001100030031-4

25X1

25X1

25X1 25X1 25X1

25X1 25X1 25X1

25X1 25X1

25X1

25X1

25X1

•	LIT RELEASABLE TO FOREIGN NATIONALS	ENG-16-006	
ATTN :	Chief, Procurement Division, GE. Contracts Administration Branch	OB JAN 1998	
2111N 2	Chief, Engineering Staff, CC	Please Return	
	Contract Task Orders 6 and 10	Engineering Sta	

1. Under the tex	ms of Contract	Task (orđez 10,	
Mary and American State of the Control of the Contr	is fabricating	ten service		
eed field sets, ier Task Order 6 is :	One	Test Power	Supply o	leveloped
is required b	y the contractor	for testing	the	field
				
2. It is request	ed that			oe .
	Test Power Suppl			
der 10. The test po	rnished equipmen wer supply is to a task.	t on Contract be returned	to the i	Task Igency
der 10. The test po on completion of thi	wer supply is to	t on Contract be returned	to the	
der 10. The test poon completion of this -E/R+D-EP/PCV:bc (2: R+D Subject File OC-E Chrono R+D Chrono	wer supply is to	be returned	to the	

CONFIDENTIAL

NOT RELEASABLE TO FOREIGN NATIONALS